

<p>0 ... A, B 0 ... -A, -B -A ... +B</p>	U_{max} A, B	I_{max}
	100 V	25 mA
	200 V	25 mA
	300 V	25 mA
	400 V	25 mA
	500 V	12 mA
	600 V	12 mA
	800 V	12 mA
	1500 V	6 mA
	5000 V	2 mA
	10000 V	1 mA